

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2664852 JIV report S/N: 0548

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

## A. GENERAL INFORMATION:

1. Fountain Incident Number: 2664852 2. Type of incident\* OIL SPILL  
3. Name of Location 14" OKORDIA - RUMUKEPE PIPELINE  
4. Name of nearest community EDEOHA 5. State: RIVERS 6. LGA AHOADA EAST  
7. Production Facility/Installation CRUDE OIL PIPELINE  
8. Asset Owner/Hub THE SHELL PETROLEUM DEVELOPMENT COMPANY  
OF NIGERIA LIMITED / PIPELINE

## B. INCIDENT INFORMATION:

9. Details of incident  
a. Date Reported: 15<sup>TH</sup> JUNE 2020  
b. Start date/time of Investigation: 18<sup>TH</sup> JUNE 2020 11:50 HRS  
c. Investigation End date: 18<sup>TH</sup> JUNE 2020 Day(s) on site: ONE (1) DAY  
d. Description of spill point environment

- |   |  |   |
|---|--|---|
| <input type="checkbox"/> Firm soil                | <input checked="" type="checkbox"/> Loose soil | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water              | <input type="checkbox"/> Swampy                | <input type="checkbox"/> Exposed pipe surface               |
| <input type="checkbox"/> Well Platform (on water) | <input type="checkbox"/> Drill Rig             | <input type="checkbox"/> Sand bag(s)                        |

Additional observations around the spill point:

THE SPILL POINT WAS FLOODED.

### e. Description of leak point (tick as applicable);

- |  |   |  |
|--|---|--|
| <input type="checkbox"/> Smooth round-edge hole                                | <input type="checkbox"/> Rough-edge hole      | <input type="checkbox"/> Hack saw cut                                      |
| <input type="checkbox"/> Complete Rupture                                      | <input type="checkbox"/> Inward dent,         | <input type="checkbox"/> Well head tampering                               |
| <input checked="" type="checkbox"/> Failed Weld-on illegal hot tap valve       | <input type="checkbox"/> Failed Clamp,        | <input type="checkbox"/> Missing Pipeline/Flowline                         |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow  | <input type="checkbox"/> Third party tampering with <b>Clamp</b>           |
| <input type="checkbox"/> Third party tampering with valve setting              | <input type="checkbox"/> Bulging Outward      | <input type="checkbox"/> Third party tampering with <b>flange.</b>         |
| <input type="checkbox"/> Flare System/Bund wall failure                        | <input type="checkbox"/> Cold vent            | <input type="checkbox"/> Surge vessel overflow,                            |
| <input type="checkbox"/> Valve Failure   | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 <sup>rd</sup> party equipment impact |
| <input type="checkbox"/> Tear (_____)  |   |  |
| <input type="checkbox"/> Others (specify) _____                                |   |  |

### f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3<sup>rd</sup> party damage   
 Operational  Others (including Mystery spills) \_\_\_\_\_

\*This can be: (a) Oil Spill (b) Drilling fluid/Chemical (c) Siltation (d) Water Leak (e) Fire (f) Non-leaking theft point removal

Version 2020/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment);  
Blue (Host Community)



# JOINT INVESTIGATION REPORT

0548

INCIDENT NO: 2064857 JIV report S/N:

a. Spill Point Coordinates ( \*Coordinates taken from the Aggregated into one Joint Investigation Report)

b. Measuring unit

WGS 84

Northing: <b>LATITUDE</b> 5.02806	Easting: <b>LONGITUDE</b> 6.61469

## C. RISK ASSESSMENT

### 10. Details of Environment

i. Type of environment where spill occurred (select one):

- Land     
  Swamp     
  Water     
  Seasonal swamp     
  Shoreline/Waterfront

ii. Type of environment to which oil has spread:

- Land <sup>FLOODED</sup>     
  Swamp     
  Waterbody (specify) \_\_\_\_\_

iii. Weather condition

- Dry     
  Wet     
  Windy     
  Hot

### 11. Distance to Sensitive habitat within 100m radius

- |   |   |     |                             |
|---|---|-----|-----------------------------|
| <input type="checkbox"/> Government reserved and designated protected area                    | [ | ,m] | } NONE SEEN WITHIN VICINITY |
| <input type="checkbox"/> Drinking water source  | [ | ,m] |                             |
| <input type="checkbox"/> Surface water <input type="checkbox"/> Borehole                      | [ | ,m] |                             |
| <input type="checkbox"/> Built up Area  | [ | ,m] |                             |
| <input type="checkbox"/> Residential Area <input type="checkbox"/> Commercial/Industrial Area | [ | ,m] |                             |
| <input type="checkbox"/> Farmlands  | [ | ,m] |                             |
| <input type="checkbox"/> Fish Farm Pond   | [ | ,m] |                             |
| <input type="checkbox"/> Fishing net  | [ | ,m] |                             |
| <input type="checkbox"/> Others (specify) _____   | [ | ,m] |                             |

### 12. Containment measures put in place:

- Booms   
  French   
  Dyke   
  Pit   
  Natural depression   
  None

Others: \_\_\_\_\_

13. Any pictures or video coverage?

[N]

14. Further response/repair initiated as at the time of JIV?

[N]

If yes to item 14, give brief description:

REPAIR ACTIVITY ONGOING.



# JOINT INVESTIGATION REPORT

INCIDENT NO: 2664852 JIV report S/N: 0548

15. Was there any disruption to the investigation? [Y]  [N]

If yes to item 15 give brief description:

NOT APPLICABLE

16. Was JIV delayed? [Y]  [N]

Reason(s):

- Delayed Community Access Approval  
  Security Challenges  
  Access constraint due to terrain  
 Others (specify) NOT APPLICABLE

**D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL**

17. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
<u>NONE WITHIN AREA OF IMPACT</u>					

18. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
<u>1</u>	<u>PALM TREE</u>	<u>—</u>	<u>—</u>	<u>✓</u>	<u>3</u>	<u>IMPACTED BY SPILL</u>

19. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
<u>NONE WITHIN AREA OF IMPACT</u>				

20. Others (Specify) e.g. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
<u>NONE WITHIN AREA OF IMPACT</u>				

**E. GRAPHIC DESCRIPTION OF LEAK POINT** (while detailed description of the leak point should be contained in the leak report, overview sketch of the site should be added as appendix 1)

SECTION OF 14" OKORDIA - RUMUEKPE PIPELINE AT EDEOMA SHOWING CRUDE OIL LEAK POINT INSTALLED AT 12 O' CLOCK POSITION BY UNKNOWN PERSONS.









JIV ALONG 14" OKORDIA TO RUMUEKPE P/L @ EDEOHA

INC. NO : 2020\_2664852

PT_ID	LONGITUDE (WGS 84)	LATITUDE (WGS 84)
SP	6.61469	5.02806
321	6.61465	5.02798
322	6.61462	5.02785
323	6.61457	5.02787
324	6.61462	5.02802
325	6.61456	5.02808
326	6.61462	5.02822
327	6.61482	5.02807
328	6.61488	5.02816
329	6.61483	5.02823
330	6.61485	5.02826
331	6.61492	5.02817
332	6.61486	5.02808
333	6.61498	5.02801
334	6.61505	5.02806
335	6.61507	5.02805
336	6.61507	5.02797
337	6.61563	5.02764
338	6.61594	5.02748
339	6.61603	5.02763
340	6.61609	5.02762
341	6.61601	5.02747
342	6.61615	5.02732
343	6.61613	5.02719
344	6.61596	5.02726
345	6.61587	5.02709
346	6.61582	5.02709
347	6.6159	5.0273
348	6.61567	5.0274
349	6.61561	5.02733
350	6.61557	5.0274
351	6.61561	5.02746
352	6.61532	5.02761
353	6.61529	5.0276
354	6.61522	5.02765
355	6.6152	5.02771
356	6.61494	5.02782

*[Handwritten signature]*



# JOINT INVESTIGATION REPORT

INCIDENT NO: 2664852 JIV report S/N: 0548

## G. INCIDENT INFORMATION:

### a. Impacted Area Details \*

- Total calculated area of impact (Ha) 0.45 HA
- Impact within SPDC R.O.W YES
- Impact outside SPDC R.O.W YES

\* Round off to 2 decimal places if area is  $\geq 100 \text{ m}^2$  or to 4 decimal places if area is  $< 100 \text{ m}^2$  (e.g. 14.55, 0.0051, 0.0009)  
\* Express in Hectares (Ha)

### b. Volume of oil recovered before completion of JIV ( $V_{rec}$ ):

Recovered oil $V_{rec}$ :	<u>NIL</u>	Barrels
---------------------------	------------	---------

Controlled recovery/evacuation from source with no impact to environment:

<u>NIL</u>	Barrels
------------	---------

### c. Net Estimated Spilled Volume $V_{Est}$ (bbls)\* =

12.31 BARRELS

Estimated Reported Volume\*\*  $V_{rep}$ (bbls)=

13 BARRELS

#### \*Notes

- Volume estimation was done using an excel based tool (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for volume estimation or cause of spill.

NOT APPLICABLE

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of  $\text{m}^3$  to barrels is Volume ( $\text{m}^3$ ) x 6.29. \*\*Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl  
Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl  
Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment);  
Blue (Host Community)

Version 2020/01

Page 5 of 8



# JOINT INVESTIGATION REPORT

INCIDENT NO: 2664852 JIV report S/N:0548

## d. General Status of the site

- i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out
- ii. Investigation of the incident site showed that there is residual impact on site requiring further works

## e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:

- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- The Shell Petroleum Development Company [SPDC]:
- *Separate DPR form has been filled out with same findings*
- *Separate NOSDRA form has been filled out with same findings*
- *Separate SME form has been filled out with same findings*


*Tick as applicable*



# JOINT INVESTIGATION REPORT

INCIDENT NO: 2664852 JIV report S/N: 548

f. Appendix 1: Overview sketch of the site



Version 2020/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment);  
Blue (Host Community)

Page 7 of 8