




Overview: Part of spill impact on 12" ImoRiver - Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation 1st July 2020.



Close-up: 3" ball valve installed with elbow at 12 o'clock to 3 o'clock position on 12" Imo River - Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation 1st July 2020.