



Overview: Part of spill impact on 4" Soku Well 23 Flowline at Ekineama 2. Picture was taken during Joint Investigation on 19th August 2020.



Close-up: Corrosion at 6 o'clock position on 4" Soku Well 23 Flowline at Ekineama 2. Picture was taken during Joint Investigation on 31st August 2020.