



Overview: Part of spill impact on Well 24 Lima Bean Box at Ojobo. Picture was taken during Joint Investigation of 25th April 2020.



Close-up: Tear due to Internal erosion on 3" Well head on Well 24 Lima Bean Box at Ojobo. Picture was taken during Joint Investigation of 25th April 2020.



Overview: Part of spill impact on Well 24 Lima Bean Box at Ojobo. Picture was taken during Joint Investigation of 25th April 2020.



Close-up: Tear due to Internal erosion on 3" Well head on Well 24 Lima Bean Box at Ojobo. Picture was taken during Joint Investigation of 25th April 2020