



Overview: Part of spill impact on 8" Nkali – ImoRiver2 Pipeline at Odagwa. Picture was taken during Joint Investigation of 4th May 2020.



Close-up: 2 nos 1" valve crude oil theft points installed 1m apart at 12 o'clock position on 8" Nkali – ImoRiver2 Pipeline at Odagwa. Picture was taken during Joint Investigation of 4th May 2020.