



2020/05/12 01:47
10m 1011hPa
S 05° 11' 55" N 006° 29' 25" E

12 05 2020 01 47

Overview: Part of spill impact on 3" Adibawa Well 6T flowline flange at Edagberi-Betterland.
Picture was taken during Joint Investigation of 12th May 2020.