



Overview: Part of spill impact on 4" ImoRiver Well 55s Flowline at Igiriukwu. Picture was taken during Joint Investigation 5th May 2020.



Close-up: Hacksaw cut at 6 o'clock position on 4" ImoRiver Well 55s Flowline at Igiriukwu. Picture was taken during Joint Investigation 5th May 2020.



Overview: Part of spill impact on 4" ImoRiver Well 55s Flowline at Igiriukwu. Picture was taken during Joint Investigation 5th May 2020.



Close-up: Hacksaw cut at 6 o'clock position on 4" ImoRiver Well 55s Flowline at Igiriukwu. Picture was taken during Joint Investigation 5th May 2020.