



Overview: Part of spill impact on 6inch Imoriver2- Imoriver1 bulkline at Odagwa . Picture was taken during Joint Investigation on 5th November 2020.



Close-up: Plugged drilled hole through a locally fabricated clamp at 2 o'clock position on 6'' Imoriver2 Imoriver1 bulkline at Odagwa . Picture was taken during Joint Investigation on 5th November 2020.