



Overview: Overview of incident environment of Estuary flow station flare at Ogulagha. Picture was taken during Joint Investigation of 1st December 2020.



Close-up: Failed flare head on Estuary flow station flare at Ogulagha. Picture was taken during Joint Investigation of 1st December 2020.