



Overview: Part of spill impact on Imo River 1 Well 44s Flowline at Igiriukwu Isi-Etithoha. Picture was taken during Joint Investigation on 15th September 2020.



Close-up: 72mm Hacksaw cut at 5 to 6 o'clock position on Imo River 1 Well 44s Flowline at Igiriukwu Isi-Etithoha. Picture was taken during Joint Investigation on 15th September 2020.