



Overview: Part of spill impact on 4" Imo River 3 Well 01T Flowline at Owaza. Picture was taken during Joint Investigation of 28<sup>th</sup> August 2021.



Close-up: 8cm Hacksaw cut from 1 to 3 o'clock position on 4" Imo River 3 Well 01T Flowline at Owaza. Picture was taken during Joint Investigation of 28<sup>th</sup> August 2021.