




Overview: Part of spill impact on 12" Imo River 2 – Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation of 28<sup>th</sup> August 2021.



Close-up: Crude oil theft point installed at 12 o'clock position on 12" Imo River 2 – Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation of 28<sup>th</sup> August 2021.