




Overview: Part of spill impact on 20" Kolocreek Pipeline at Okporowo.  
 Picture was taken during Joint Investigation of 5<sup>th</sup> August 2021.



Close-up: 3" ball valve with 2" extension pipe installed at 12 o'clock position on 20" Kolocreek Pipeline at Okporowo. Picture was taken during Joint Investigation of 5<sup>th</sup> August 2021.