



Overview: Part of spill impact on 36" Bomu Bonny Pipeline at Eneka.
Picture was taken during Joint Investigation of 3rd December 2021.



Close-up: 2inch ball valve and 2inch nipple with a distance of 0.2m apart installed at 12 o'clock position on 36" Bomu Bonny Pipeline at Eneka.
Picture was taken during Joint Investigation of 4th December 2021.