



Overview: Part of spill impact on 4" Imo River Well 64L Flowline at Igiriukwu-Owaza.
Picture was taken during Joint Investigation on 15th December 2021.



Close-up: 2" Ball valve attached to a local fabricated clamp installed at 12 o'clock position on 4" Imo River Well 64L Flowline at Igiriukwu-Owaza.
Picture was taken during Joint Investigation on 15th December 2021.