



Overview: Part of spill impact on 12inch Imo River Ogale Pipeline . Picture was taken during Pre-Joint Investigation of 14<sup>th</sup> February 2021.



Close-up: Plugged 2inch Crude oil theft point installed at 12 o'clock position on 12inch Imo River Ogale Pipeline . Picture was taken during Joint Investigation of 15<sup>th</sup> February 2021.