



Overview: Part of spill impact on 16inch Assa Egbema Pipeline at Obiakpu . Picture was taken during Joint Investigation of 20<sup>th</sup> February 2021.



Close-up: Crude oil theft point installed at 12 o'clock position on 16inch Assa Egbema Pipeline at Obiakpu . Picture was taken during Joint Investigation of 20<sup>th</sup> February 2021.