



Overview: Part of spill impact on 6inch Imo River Well 26s Flowline at Owaza. Picture was taken during Joint Investigation of 20th February 2021.



Close-up: 1.5inch Crude oil theft valve installed at 12 o'clock position on 6inch Imo River Well 26s Flowline at Owaza. Picture was taken during Joint Investigation of 20th February 2021.