



Overview: Part of spill impact on 4inch Imo River well 22s Flowline at Owaza. Picture was taken during Joint Investigation of 11th January 2021.



Close-up: Hacksaw cut from 7o'clock to 11o'clock position on 4inch Imo River well 22s Flowline at Owaza. Picture was taken during Joint Investigation of 11th January 2021.