



Overview: Part of spill impact on 6inch Kanbo Well 7s flowline at Agbidiama. Picture was taken during Joint Investigation of 29<sup>th</sup> January 2021.



Close-up: 2 nos hacksaw cuts at 12 o'clock and 3 o'clock position on 6inch Kanbo Well 7s flowline at Agbidiama. Picture was taken during Joint Investigation of 29<sup>th</sup> January 2021.