



Overview: Part of spill impact on 12inch Oguta Egbema Pipeline at Opuoma . Picture was taken during Joint Investigation of 16th January 2021.



Close-up: Inward dent and crack at 1 o'clock position on 12inch Oguta Egbema Pipeline at Opuoma . Picture was taken during Joint Investigation of 16th January 2021.