




Overview: Part of spill impact on 24inch Bomu Bonny Trans Niger Pipeline at Owokiri.  
Picture was taken during Joint Investigation of 8<sup>th</sup> June 2021.



Close-up: 6inch valve flange leaking at the nipple flange installed at 3 o'clock position on 24inch Bomu Bonny Trans Niger Pipeline at Owokiri.  
Picture was taken during Joint Investigation of 8<sup>th</sup> June 2021.