

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2966435 JIV report S/N: 0000790

(Note: As practicable as possible the JIV report is to be signed in the field by all the participating parties)

## A. GENERAL INFORMATION:

1. Fountain Incident Number: 2966435 2. Type of incident\* OIL SPILL  
3. Name of Location 18" ASSA - RUMUERPPE PIPELINE  
4. Name of nearest community EGBEDA 5. State: RIVERS 6. LGA IMOHUA  
7. Production Facility/Installation OIL PIPELINE  
8. Asset Owner/Hub THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED (SPDC)/PIPELINE

## B. INCIDENT INFORMATION:

9. Details of incident  
a. Date Reported: 5TH JUNE, 2021  
b. Start date/time of Investigation: 7TH JUNE, 2021 / 1300HRS  
c. Investigation End date: 7TH JUNE, 2021 Day(s) on site: ONE (1) DAY  
d. Description of spill point environment

- |   |  |   |
|---|--|---|
| <input type="checkbox"/> Firm soil                | <input checked="" type="checkbox"/> Loose soil | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water              | <input type="checkbox"/> Swampy                | <input type="checkbox"/> Exposed pipe surface               |
| <input type="checkbox"/> Well Platform (on water) | <input type="checkbox"/> Drill Rig             | <input type="checkbox"/> Sand bag(s)                        |

Additional observations around the spill point:

NOT APPLICABLE

## e. Description of leak point (tick as applicable);

- |  |   |  |
|--|---|--|
| <input type="checkbox"/> Smooth round-edge hole                                | <input type="checkbox"/> Rough-edge hole      | <input type="checkbox"/> Hack saw cut                                      |
| <input type="checkbox"/> Complete Rupture                                      | <input type="checkbox"/> Inward dent,         | <input type="checkbox"/> Well head tampering                               |
| <input checked="" type="checkbox"/> Failed Weld-on illegal hot tap valve       | <input type="checkbox"/> Failed Clamp,        | <input type="checkbox"/> Missing Pipeline/Flowline                         |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow  | <input type="checkbox"/> Third party tampering with Clamp                  |
| <input type="checkbox"/> Third party tampering with valve setting              | <input type="checkbox"/> Bulging Outward      | <input type="checkbox"/> Third party tampering with flange,                |
| <input type="checkbox"/> Flare System/Bund wall failure                        | <input type="checkbox"/> Cold vent            | <input type="checkbox"/> Surge vessel overflow,                            |
| <input type="checkbox"/> Valve Failure   | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 <sup>rd</sup> party equipment impact |
| <input type="checkbox"/> Tear ( _____ )  |   |  |
| <input type="checkbox"/> Others (specify): _____                               |   |  |

## f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3<sup>rd</sup> party damage   
 Operational  Others (including Mystery spills) \_\_\_\_\_

\*This can be: (a) Oil Spill (b) Drilling fluid/Chemical (c) Siltation (d) Water Leak (e) Fire (f) Non-leaking theft point removal

Version 2020/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

# JOINT INVESTIGATION REPORT

0000790

INCIDENT NO: 2966435 JIV report S/N:

g. Spill Point Coordinates (\*Incidents <100m apart to be aggregated into one Joint Investigation Report)

h. Measuring unit KGS 84

Northing: <u>LATITUDE</u>	Easting: <u>LONGITUDE</u>
<u>5.26492</u>	<u>6.77583</u>
/	/

## C. RISK ASSESSMENT

### 10. Details of Environment

i. Type of environment where spill occurred (select one):

- Land     
  Swamp     
  Water     
  Seasonal swamp     
  Shoreline/Waterfront

ii. Type of environment to which oil has spread:

- Land     
  Swamp     
  Waterbody (specify) \_\_\_\_\_

iii. Weather condition

- Dry     
  Wet     
  Windy     
  Hot

### 11. Distance to Sensitive habitat within 100m radius

- |   |       |
|---|-------|
| <input type="checkbox"/> Government reserved and designated protected area                    | [ ,m] |
| <input type="checkbox"/> Drinking water source  | [ ,m] |
| <input type="checkbox"/> Surface water <input type="checkbox"/> Borehole                      |       |
| <input type="checkbox"/> Built up Area  | [ ,m] |
| <input type="checkbox"/> Residential Area <input type="checkbox"/> Commercial/Industrial Area |       |
| <input type="checkbox"/> Farmlands  | [ ,m] |
| <input type="checkbox"/> Fish Farm/Pond   | [ ,m] |
| <input type="checkbox"/> Fishing net  | [ ,m] |
| <input type="checkbox"/> Others (specify) _____   | [ ,m] |

} NONE SEEN WITHIN VICINITY

### 12. Containment measures put in place:

- Booms   
  Trench   
  Dyke   
  Pit   
  Natural depression   
  None
- Others: \_\_\_\_\_

13. Any pictures or video coverage?

[N]

14. Further response/repair initiated as at the time of JIV?

[N]

If yes to item 14, give brief description:

CRUDE OIL RECOVERY AND REPAIR ACTIVITIES

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2966435 JIV report S/N: 0000790

15. Was there any disruption to the investigation? [Y]  [N]

If yes to item 15 give brief description:

NOT APPLICABLE

16. Was JIV delayed? [Y]  [N]

Reason(s):

- Delayed Community Access Approval     Security Challenges     Access constraint due to terrain  
 Others (specify) NOT APPLICABLE

**D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL**

17. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
NONE WITHIN AREA OF IMPACT					

18. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
NONE WITHIN AREA OF IMPACT						


19. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
NONE WITHIN AREA OF IMPACT				

20. Others (Specify) e.g. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
NONE WITHIN AREA OF IMPACT				

**E. GRAPHIC DESCRIPTION OF LEAK POINT** (while detailed description of the leak point should be contained in the leak report, overview sketch of the site should be added as appendix 1) A SECTION OF 18" ASSA-RUMYEKPE PIPELINE AT EGBEDA SHOWING A 3" BALL VALVE INSTALLED AT 12 O'CLOCK POSITION BY UNKNOWN PERSONS.



FROM ASSA - RumyeKpe

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2966435 JIV report S/N: 0000790

**F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION**

21. Impacted area boundary Coordinates *(If more, Print and attach as Appendix)*

S/N	Northing	Easting

SEE ATTACHED COPY FOR COORDINATES LIST

PNT_ISD	LAT	LONG
54	5.2649	6.77593
55	5.26489	6.77589
56	5.26481	6.77585
57	5.26489	6.77579
58	5.26495	6.77579
59	5.26505	6.77583
60	5.26504	6.77585
61	5.26498	6.77584
62	5.26499	6.77585
63	5.265	6.77587
64	5.26508	6.7759
65	5.26509	6.77594
66	5.26539	6.77598
67	5.2655	6.77597
68	5.26578	6.77601
69	5.26583	6.77605
70	5.26595	6.77608
71	5.26621	6.77616
72	5.26627	6.77621
73	5.26619	6.7762
74	5.26611	6.77615
75	5.26609	6.7762
76	5.26596	6.77618
77	5.26594	6.77613
78	5.26579	6.77611
79	5.26567	6.7761
80	5.2656	6.77609
81	5.26557	6.77606
82	5.26549	6.77625
83	5.26548	6.77623
84	5.26554	6.77611
85	5.26554	6.77606
SP	5.26492	6.77583

*Handwritten signature*

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2966435 JIV report S/N: 0000790

**G. INCIDENT INFORMATION:**

**a. Impacted Area Details \***

- Total calculated area of impact (Ha) 0.13 Ha
- Impact within SPDC R.O.W. YES
- Impact outside SPDC R.O.W. YES

\* Round off to 2 decimal places if area is  $\geq 100 \text{ m}^2$  or to 4 decimal places if area is  $< 100 \text{ m}^2$  (e.g. 14.55, 0.0051, 0.0009)  
 \* Express in Hectares (Ha)

**b. Volume of oil recovered before completion of JIV ( $V_{rec}$ ):**

Recovered oil ( $V_{rec}$ )	Barrels
<u>1 BARREL</u>	

Controlled recovery/evacuation from source with no impact to environment:


<u>NIL</u>	Barrels
------------	---------

c. Net Estimated Spilled Volume ( $V_{est}$ ) (bbbls) = <u>3.44 BARRELS</u>
Estimated Reported Volume** ( $V_{rep}$ ) (bbbls) = <u>4 BARRELS</u>

**\*Notes:**

- Volume estimation was done using an excel-based tool. (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for volume estimation or cause of spill:



Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of  $\text{m}^3$  to barrels is  $\text{Volume (m}^3) \times 6.29$ ; \*\*Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl — Reported volume = 16 bbl  
 Calculated volume = 0.35 bbl — Reported volume = 0.4 bbl  
 Calculated volume = 0.01 bbl — Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Version:2020/01

Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community).

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2966435 JIV report S/N: 0000790

## d. General Status of the site

- |  |
|--|
| i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/> |
| ii. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/>  |

## e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:


- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- The Shell Petroleum Development Company [SPDC]:
- *Separate DPR form has been filled out with same findings*
- *Separate NOSDRA form has been filled out with same findings*
- *Separate SME form has been filled out with same findings*

*Tick as applicable*

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2966435 JIV report S/N: 0000790

f. Appendix 1: Overview sketch of the site



Version 2020/01