



Overview: Part of spill impact on 4inch Mini Nta Well 2T Flowline at Elele Alimini. Picture was taken during Joint Investigation of 10th June 2021.



Close-up: 8cm Hacksaw cut at 11-12 o'clock position on 4inch Mini Nta Well 2T Flowline at Elele Alimini. White polythene tape was removed to allow inspection of the damage to the pipe and facilitate repair. Picture was taken during Joint Investigation of 10th June 2021