



Overview: Part of spill impact on Ajatiton Well 1 Lima at Azagbene.
Picture was taken during Joint Investigation of 23rd June 2021.



Close-up: Hacksaw cut at 12 o'clock position at hook up arm on Ajatiton Well 1 Lima at Azagbene.
Picture was taken during Joint Investigation of 23rd June 2021.