



Overview: Part of spill impact on 3inch Opukushi Well 12 L/S Flowline at Agbidiana.  
Picture was taken during Joint Investigation of 28<sup>th</sup> June 2021.



Close-up: Hacksaw cut at 12 o'clock position on 3inch Opukushi Well 12 L/S Flowline at Agbidiana.  
Picture was taken during Joint Investigation of 28<sup>th</sup> June 2021.