




Overview: Part of spill impact on Adibawa North East Well 1 Flowline at Biseni.
Picture was taken during Joint Investigation of 23rd June 2021.



Closeup 1: One of three nos spill points puncture on Adibawa North East Well 1 Flowline at Biseni. Picture was taken during Joint Investigation of 23rd June 2021.



Closeup 2: Two of three nos spill points puncture on Adibawa North East Well 1 Flowline at Biseni. Picture was taken during Joint Investigation of 23rd June 2021.



Closeup 3: Three of Three nos spill points puncture on Adibawa North East Well 1 Flowline at Biseni. Picture was taken during Joint Investigation of 23rd June 2021.