




Overview: Part of spill impact on Adibawa Well 10s flowline at Edagberi.  
Picture was taken during Joint Investigation of 23<sup>rd</sup> June 2021.



Close-up: Hacksaw at 5 o'clock position on Adibawa Well 10s flowline at Edagberi.  
Picture was taken during Joint Investigation of 23<sup>rd</sup> June 2021.