




Overview: Part of spill impact on Opukushi Well 24T Wellhead at Agbidiana.  
Picture was taken during Joint Investigation of 22<sup>nd</sup> June 2021.



Close-up: Tampered valve on Opukushi Well 24T Wellhead at Agbidiana.  
Picture was taken during Joint Investigation of 22<sup>nd</sup> June 2021.