



Overview: Part of spill impact on 12inch Imo River2 – Imo River1 Pipeline at Odagwa. Picture was taken during Joint Investigation of 4th March 2021.



Close-up: Crude oil theft point installed at 12 o'clock position on 12inch Imo River2 – Imo River1 Pipeline at Odagwa. Picture was taken during Joint Investigation of 4th March 2021.