



Overview: Part of spill impact on 4inch Nkali well 13L/S flowline at Odagwa 2.
Picture was taken during Joint Investigation of 26th March 2021.



Close-up: SP 1 : Crude oil theft points installed at 3 and 9 o'clock position on 4inch Nkali well 13L/S flowline at Odagwa 2. Picture was taken during Joint Investigation of 26th March 2021.



Closeup: SP 2: Crude oil theft points installed at 3 and 9 o'clock position on 4inch Nkali well 13L/S flowline at Odagwa 2. Picture was taken during Joint Investigation of 26th March 2021.