



Overview: Part of spill impact on 4inch Nkali well 10S flowline at Odagwa .  
Picture was taken during Joint Investigation of 26<sup>th</sup> March 2021.



Close-up: SP 1 : Crude oil theft point installed at 12 o'clock position on 4inch Nkali well 10S flowline  
at Odagwa . Picture was taken during Joint Investigation of 26<sup>th</sup> March 2021.