



Overview: Part of spill impact on 3inch Imo River Well 63T Flowline at Owaza. Picture was taken during Joint Investigation of 10th April 2021.



Close-up: Pinhole at 7 o'clock position on 3inch Imo River Well 63T Flowline at Owaza. Picture was taken during Joint Investigation of 12th April 2021.