



Overview: Part of spill impact on 18inch Assa Rumuekpe Pipeline at Ochia .  
Picture was taken during Joint Investigation of 4<sup>th</sup> May 2021.



Close-up: 2nos of 2inch non leaking ball valves and 2nos of 2inch leaking ball valves installed at 12 o'clock position on 18inch Assa Rumuekpe Pipeline at Ochia . Picture was taken during Joint Investigation of 4<sup>th</sup> May 2021.