



Overview: Part of spill impact on 8inch Afam Well 27T flowline at Egberu. Picture was taken during Joint Investigation of 15<sup>th</sup> May 2021.



Close-up: A failed Clamp installed to repair a previous clamp incident on 8inch Afam Well 27T flowline at Egberu. Picture was taken during Joint Investigation of 15<sup>th</sup> May 2021.