



Overview: Part of spill impact on 4" Otumara Well 29S Flowline at Otumara.
Picture was taken during Joint Investigation on 21st December 2021.



Overview: Part of spill impact on 4" Otumara Well 29S Flowline at Otumara.
Picture was taken during Joint Investigation on 21st December 2021.



Close-up: Pin hole due to corrosion at 6 o'clock position on 4" Otumara Well 29S Flowline at Otumara. Picture was taken during Joint Investigation on 21st December 2021.