

JOINT INVESTIGATION REPORT

INCIDENT NO: 3059858 JIV report S/N: 0000971

(Note: As practicable as possible the JIV report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:

1. Fountain Incident Number: 3059858 2. Type of incident* OIL SPILL
3. Name of Location 28" OGALE - BOMU PIPELINE
4. Name of nearest community AGBONCITA 5. State: RIVERS 6. LGA ELEME
7. Production Facility/Installation CRUDE OIL PIPELINE
8. Asset Owner/Hub THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED (SPDC) PIPELINE

B. INCIDENT INFORMATION:

9. Details of incident
a. Date Reported: 4th NOVEMBER, 2021
b. Start date/time of Investigation: 5th NOVEMBER 2021/14:18HRS
c. Investigation End date: 5th NOVEMBER 2021 Day(s) on site: ONE DAY
d. Description of spill point environment
 Firm soil Loose soil Recently excavated area
 Under water Swampy Exposed pipe surface
 Well Platform (on water) Drill Rig Sand bag(s)

Additional observations around the spill point:

NOT APPLICABLE

e. Description of leak point (tick as applicable);

- | | | |
|--|---|--|
| <input type="checkbox"/> Smooth round-edge hole | <input type="checkbox"/> Rough-edge hole | <input type="checkbox"/> Hack saw cut |
| <input type="checkbox"/> Complete Rupture | <input type="checkbox"/> Inward dent, | <input type="checkbox"/> Well head tampering |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve | <input type="checkbox"/> Failed Clamp, | <input type="checkbox"/> Missing Pipeline/Flowline |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow | <input type="checkbox"/> Third party tampering with Clamp |
| <input type="checkbox"/> Third party tampering with valve setting | <input type="checkbox"/> Bulging Outward | <input type="checkbox"/> Third party tampering with flange, |
| <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Cold vent | <input type="checkbox"/> Surge vessel overflow, |
| <input type="checkbox"/> Valve Failure | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 rd party equipment impact |
| <input type="checkbox"/> Tear (_____) | | |
| <input type="checkbox"/> Others (specify) _____ | | |

f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3rd party damage
 Operational Others (including Mystery spills) _____

*This can be: (a) Oil Spill (b) Drilling fluid/Chemical (c) Situation (d) Water Leak (e) Fire (f) Non-leaking theft point removal
Version 2020/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NDSORA); Yellow (State Ministry of Environment);
Blue (Host Community)

JOINT INVESTIGATION REPORT

000971

INCIDENT NO: 3059858 JIV report S/N:

g. Spill Point Coordinates (**Incidents ≤ 100m apart to be aggregated into one Joint Investigation Report*)

h. Measuring unit

(WGS 84)

| Northing: | Easting: |
|-----------|-----------|
| 4.7954876 | 7.1275023 |
| / | / |

C. RISK ASSESSMENT

10. Details of Environment

i. Type of environment where spill occurred (select one):

- Land
 Swamp
 Water
 Seasonal swamp
 Shoreline/Waterfront

ii. Type of environment to which oil has spread:

- Land
 Swamp
 Waterbody (specify) _____

iii. Weather condition

- Dry
 Wet
 Windy
 Hot

11. Distance to Sensitive habitat within 100m radius

- Government reserved and designated protected area [,m]
 Drinking water source [,m]
 Surface water Borehole
 Built up Area [90 ,m]
 Residential Area Commercial/Industrial Area
 Farmlands [,m]
 Fish Farm/Pond [,m]
 Fishing net [,m]
 Others (specify) _____ [,m]

12. Containment measures put in place:

- Booms
 Trench
 Dyke
 Pit
 Natural depression
 None
 Others: NOT APPLICABLE

13. Any pictures or video coverage?

[N]

14. Further response/repair initiated as at the time of JIV?

[N]

If yes to item 14, give brief description:

REPAIR BY CLAMPING ON-GOING

JOINT INVESTIGATION REPORT

INCIDENT NO: 3059858 JIV report S/N: 0000971

15. Was there any disruption to the investigation? [Y] [N]

If yes to item 15 give brief description:

NOT APPLICABLE

16. Was JIV delayed? [Y] [N]

Reason(s):

- Delayed Community Access Approval Security Challenges Access constraint due to terrain
 Others (specify) NOT APPLICABLE

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

17. Structures / Properties

| S/N | Type of Structures | Description | Size | Number | Comments |
|--|--------------------|-------------|------|--------|----------|
| <u>NONE SEEN WITHIN AREA OF IMPACT</u> | | | | | |

18. Crops/Economic Trees

| S/N | Type of crops | Young | Medium | Matured | Quantity | Comments |
|--|---------------|-------|--------|---------|----------|----------|
| <u>NONE SEEN WITHIN AREA OF IMPACT</u> | | | | | | |

19. Fish/Nets/Ponds


| S/N | Fish/Nets/Ponds | Description | Quantity/Size | Comments |
|--|-----------------|-------------|---------------|----------|
| <u>NONE SEEN WITHIN AREA OF IMPACT</u> | | | | |

20. Others (Specify) e.g. Animal Traps

| S/N | Others | Description | Quantity/Size | Comments |
|--|--------|-------------|---------------|----------|
| <u>NONE SEEN WITHIN AREA OF IMPACT</u> | | | | |

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detailed description of the leak point should be contained

in the leak report, overview sketch of the site should be added as appendix 1) A SECTION OF 28" OGALE-BORU PIPELINE AT AGBONCHIA SHOWING A 2" NIPPLE INSTALLED AT 12 O'CLOCK POSITION BY UNKNOWN PERSON(S).



JOINT INVESTIGATION REPORT

INCIDENT NO: 3059858 JIV report S/N: 0000971

G. INCIDENT INFORMATION:

a. Impacted Area Details *

- Total calculated area of impact (Ha) 0.02HA
- Impact within SPDC R.O.W YES
- Impact outside SPDC R.O.W YES

* Round off to 2 decimal places if area is $\geq 100 \text{ m}^2$ or to 4 decimal places if area is $< 100 \text{ m}^2$ (e.g. 14.55, 0.0051, 0.0009)
* Express in Hectares (Ha)

b. Volume of oil recovered before completion of JIV (V_{rec}):

Recovered Oil Volume NIL Barrels

Controlled recovery/evacuation from source with no impact to environment:

NIL Barrels

| |
|--|
| Estimated Spilled Volume $V_{\text{sp}}(\text{bbls}) =$ <u>1 BARRELS</u> |
| Estimated Reported Volume $V_{\text{rep}}(\text{bbls}) =$ <u>1 BARRELS</u> |

*Notes:

- Volume estimation was done using an excel based tool. (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for volume estimation or cause of spill:

NOT APPLICABLE

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m^3) $\times 6.29$; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl — Reported volume = 16 bbl
Calculated volume = 0.35 bbl — Reported volume = 0.4 bbl
Calculated volume = 0.01 bbl — Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for volume estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Version 2020/01

Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment);
Blue (Host Community) Page 5 of 8

JOINT INVESTIGATION REPORT

INCIDENT NO: 3059858 JIV report S/N: 1000971

d. General Status of the site

| |
|--|
| i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/> |
| ii. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/> |

e. Representatives

| |
|---|
| <p>This report was <u>filled</u>, <u>agreed</u> and <u>signed</u> by the following joint investigation team representatives:</p> <ul style="list-style-type: none">• Host Community: <input checked="" type="checkbox"/>• Department of Petroleum Resources [DPR]: <input type="checkbox"/>• National Oil Spill Detection and Response Agency [NOSDRA]: <input checked="" type="checkbox"/>• State Ministry of Environment [SME]: <input checked="" type="checkbox"/>• The Shell Petroleum Development Company [SPDC]: <input checked="" type="checkbox"/>• Separate DPR form has been filled out with same findings <input type="checkbox"/>• Separate NOSDRA form has been filled out with same findings <input checked="" type="checkbox"/>• Separate SME form has been filled out with same findings <input checked="" type="checkbox"/> <p style="text-align: right;"><i>Tick as applicable</i></p> |
|---|

JOINT INVESTIGATION REPORT

INCIDENT NO: 3059858 JIV report S/N: 0000971

f. Appendix 1: Overview sketch of the site

