INCIDENT NO: 3053329 JIV report S/N:0001019

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

	GENERAL INFORMATION:			
1. I	Fountain Incident Number: 30533	29 2. Type of inci	ident* OIL SPILL	
3. 1	Name of Location AJATITON	WELL IL	FLOW LINE	
4. N	Name of nearest community OPUK USH	1 5. State: BAYELSA	6.LGA EKEREMO	
	roduction Facility/Installation FLC			
	Carried Organia	7/Aug. 6 (85)	EVEL BOLLET COLLOR	1
8. A UI G B. I	sset Owner/Hub <u>THE SHELL PE</u> ERIA LIMITED / WEST A NCIDENT INFORMATION:	SSET	WELDPMENT COMP	11
9. D	etails of incident			
a	Date Reported: 27" OCTOBERIA	2021	70. Ale	
t	o. Start date/time of Investigation: 5 TH NO	NEMBER, 2021 1	47 2:05 PM	
c	. Investigation End date: 5 TH NOVEMBE	R, 2021 Day(s) or	n site: ONE CI) DAY	
d	. Description of spill point environment			
	□Firm soil □Loose	soil	Recently excavated area	
	□Under water □Swam	ру	Exposed pipe surface	
	☐Well Platform (on water) ☐Drill		Sand bag(s)	
	1			
e	Description of leak point (tick as applicable):			
e.	Description of leak point (tick as applicable); Smooth round-edge hole	□Rough-edge hole	☐ Hack saw cut	6
e.		☐Rough-edge hole ☐ Inward dent,	☐ Hack saw cut ☐ Well head tampering	
e.	☐ Smooth round-edge hole ☐ Complete Rupture ☐ Failed Weld-on illegal hot tap valve			
e.	☐ Smooth round-edge hole ☐ Complete Rupture ☐ Failed Weld-on illegal hot tap valve ☐ Crude oil theft (illegal bunkering) point,	☐ Inward dent, ☐ Failed Clamp, ☐ Saver-pit over flow	 □ Well head tampering □ Missing Pipeline/Flowline □ Third party tampering with Clamp 	
e.	Smooth round-edge hole Complete Rupture Failed Weld-on illegal hot tap valve Crude oil theft (illegal bunkering) point, Third party tampering with valve setting	☐ Inward dent, ☐ Failed Clamp, ☐ Saver-pit over flow ☐ Bulging Outward	 □ Well head tampering □ Missing Pipeline/Flowline □ Third party tampering with Clamp □ Third party tampering with flange, 	
e.	☐ Smooth round-edge hole ☐ Complete Rupture ☐ Failed Weld-on illegal hot tap valve ☐ Crude oil theft (illegal bunkering) point, ☐ Third party tampering with valve setting ☐ Flare System/Bund wall failure	☐ Inward dent, ☐ Failed Clamp, ☐ Saver-pit over flow ☐ Bulging Outward ☐ Cold vent	☐ Well head tampering ☐ Missing Pipeline/Flowline ☐ Third party tampering with Clamp ☐ Third party tampering with flange, ☐ Surge vessel overflow,	
e.	□ Smooth round-edge hole □ Complete Rupture □ Failed Weld-on illegal hot tap valve □ Crude oil theft (illegal bunkering) point, □ Third party tampering with valve setting □ Flare System/Bund wall failure □ Valve Failure	☐ Inward dent, ☐ Failed Clamp, ☐ Saver-pit over flow ☐ Bulging Outward ☐ Cold vent ☐ Relief valve failure	 □ Well head tampering □ Missing Pipeline/Flowline □ Third party tampering with Clamp □ Third party tampering with flange, 	ct
e.	□ Smooth round-edge hole □ Complete Rupture □ Failed Weld-on illegal hot tap valve □ Crude oil theft (illegal bunkering) point, □ Third party tampering with valve setting □ Flare System/Bund wall failure □ Valve Failure	☐ Inward dent, ☐ Failed Clamp, ☐ Saver-pit over flow ☐ Bulging Outward ☐ Cold vent ☐ Relief valve failure	☐ Well head tampering ☐ Missing Pipeline/Flowline ☐ Third party tampering with Clamp ☐ Third party tampering with flange, ☐ Surge vessel overflow,	ct
	☐ Smooth round-edge hole ☐ Complete Rupture ☐ Failed Weld-on illegal hot tap valve ☐ Crude oil theft (illegal bunkering) point, ☐ Third party tampering with valve setting ☐ Flare System/Bund wall failure ☐ Valve Failure	☐ Inward dent, ☐ Failed Clamp, ☐ Saver-pit over flow ☐ Bulging Outward ☐ Cold vent ☐ Relief valve failure	☐ Well head tampering ☐ Missing Pipeline/Flowline ☐ Third party tampering with Clamp ☐ Third party tampering with flange, ☐ Surge vessel overflow,	ct
	Smooth round-edge hole □Complete Rupture □Failed Weld-on illegal hot tap valve □Crude oil theft (illegal bunkering) point, □ Third party tampering with valve setting □ Flare System/Bund wall failure □ Valve Failure □ Tear () □Others (specify) FAILED FLAT	☐ Inward dent, ☐ Failed Clamp, ☐ Saver-pit over flow ☐ Bulging Outward ☐ Cold vent ☐ Relief valve failure	☐ Well head tampering ☐ Missing Pipeline/Flowline ☐ Third party tampering with Clamp ☐ Third party tampering with flange, ☐ Surge vessel overflow, ☐ Accidental 3 rd party equipment impart	ct
	Smooth round-edge hole □Complete Rupture □Failed Weld-on illegal hot tap valve □Crude oil theft (illegal bunkering) point, □ Third party tampering with valve setting □ Flare System/Bund wall failure □ Valve Failure □ Tear () □Others (specify) FAILED FLAT	☐ Inward dent, ☐ Failed Clamp, ☐ Saver-pit over flow ☐ Bulging Outward ☐ Cold vent ☐ Relief valve failure NGC	☐ Well head tampering ☐ Missing Pipeline/Flowline ☐ Third party tampering with Clamp ☐ Third party tampering with flange, ☐ Surge vessel overflow, ☐ Accidental 3 rd party equipment imparts dental 3 rd party damage ☐)	ct
f.	Smooth round-edge hole Complete Rupture Failed Weld-on illegal hot tap valve Crude oil theft (illegal bunkering) point, Third party tampering with valve setting Flare System/Bund wall failure Valve Failure Tear (☐ Inward dent, ☐ Failed Clamp, ☐ Saver-pit over flow ☐ Bulging Outward ☐ Cold vent ☐ Relief valve failure Theft ☐; Line theft ☐; Accidenty spills)	☐ Well head tampering ☐ Missing Pipeline/Flowline ☐ Third party tampering with Clamp ☐ Third party tampering with flange, ☐ Surge vessel overflow, ☐ Accidental 3 rd party equipment imparts dental 3 rd party damage ☐)	ct
f. *This co	Smooth round-edge hole □Complete Rupture □Failed Weld-on illegal hot tap valve □Crude oil theft (illegal bunkering) point, □ Third party tampering with valve setting □ Flare System/Bund wall failure □ Valve Failure □ Tear () □Others (specify) FAILED FLAT	☐ Inward dent, ☐ Failed Clamp, ☐ Saver-pit over flow ☐ Bulging Outward ☐ Cold vent ☐ Relief valve failure Theft ☐; Line theft ☐; Accidented by the spills) ☐ Water Leak (e) Fire (f) Non-leak	☐ Well head tampering ☐ Missing Pipeline/Flowline ☐ Third party tampering with Clamp ☐ Third party tampering with flange, ☐ Surge vessel overflow, ☐ Accidental 3 rd party equipment imparts the surge of the surg	ct

Page 1 of 8

001019

INCIDENT NO: 3053329 JIV report S/N:

11. 14	Northing:		M	GS (8H Easting:		
		LATITU	DE	Zusting.	LOW	GITUDE
	4.	87643	33	. 5.	85	8449
	K ASSESSME					
10.	Details of Env	rironment				
i.	Type of er	vironment where	spill occurred (se	lect one):		
	Land	Swamp	□Water	☐Seasonal	swamp	☐Shoreline/Waterfi
ii.	Type of e	nvironment to which	ch oil has spread:			
	Land	□Swamp	□Waterbody ((specify)		
iii.	Weather c	ondition				
	□Dry	□Wet	□Windy	Uttot		
11.		nsitive habitat with		LUTIO		
	☐ Drinking · ☐Surf ☐ Built up A	ace water Boi trea dential Area Coi (/Pond t	gnated protected ar rehole mmercial/Industrial A	j ı	,m] ,m] ,m] ,m] ,m] ,m]	NONE SEE WITHIN TO
12. (Containment me	asures put in place:			,1	
	⊠Booms □	Trench Dyke		al depression	None	
12						
		video coverage?		[14]	N]	
		e/repair initiated as a	t the time of JIV?	[Y] [NT	
es to ite	em 14, give brief o	lescription:	OT AF	PPLICA	BLE	2

Blue (Host Community)

Page 2 of 8

INCIDENT NO: 3053329 JIV report S/N: 0001019

15. Was there any			5.54	[Y]	[N-		
yes to hem 15 give on			MOT	APP21	CAB	15	-
16. Was JIV delay	ed?	[V] [N]					
		(-) []					
Reason(s): Delayed Com	nunity A	ccess Approval	D'Securi	ty Challenges	☐ Acc	ess constraint due to te	rrain
Others (specify							
D TVPE/NUMBE	RSOFF	ROPERTIES	IF ANY FO	UND WITHIN	THE AR	REA OF SPREAD OF	OII
17. Structures / Pro		NOT ENTIES,	n Am, ro	CIVE WITHIN	THE ALL		
N Type of Structi	ires	Description	Size	Number		Comments	
110 110		47.		-4 5			
NONE	10	JITTHA	HX	EH O	F-1	MPACI	
18. Crops/Economic	-						
/N Type of crops	Young	100	Medium	Matured	Quant	Comments	1000
NONE	W	THIN	AR	EA O	F	MPHCI	
19. Fish/Nets/Ponds							
/N Fish/Nets/Ponds	De	escription		Quantity/Size	Comme	nts	
NONE	W	ITHIN	AR	EA C	F	IMPACT	
20. Others (Specify)							
N Others	De	scription	2	Quantity/Size	Commo	ents	
NONE	1	ITHIM		EA O	P .	MAKCI	_
GRAPHIC DESCRIP he leak report, overview				AND THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED I		•	
he leak report, overviev SECTIOM (F A	9 TATITO	AL LIF	ELL IL	FLO	WLINE F	10
KUSHI SHOW							
KUSIII SIIO	47706	77112	C D I				
			S	9			
vis (
The Contract of the Contract o							
1							

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Page 3 of 8

Blue (Host Community)

INCIDENT NO: 3053329 JIV report S/N: 001019

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

21. Impacted area boundary Coordinates (If more, Print and attach as Appendix)

Northing	Easting
11. 87 6423	5.858449
	5.858403
	5 85 84 03
	5 858474
	5.858455
4 810426	5.858426
/	/
/	
	Northing 4. 87 6433 4. 87 6425 4. 87 6457 4. 876425 4. 87.6426

Distribution of capies: White (Asset Owner), Pink (DPR), Green (NOSDRA); Yellow (State Ministry of Environment);

Blue (Host Community)

Page 4 of 8

INCIDENT NO: 3053329 JIV report S/N: 0001019

G. INCIDENT INFORMATION:
a. Impacted Area Details *
 Total calculated area of impact (Ha)O·OD17 + Ha
b. Volume of oil recovered before completion of JIV (V _{recJ}): Barrels
Recovered oil V _{recJ} : All
Controlled recovery/evacuation from source with no impact to environment:
c. Net Estimated Spilled Volume V _{Est} (bbls)* =
Estimated Reported Volume** V _{rep} (bbls)= O· 1 BARREL O· 1 BARREL
Estimated Reported Volume** V _{rep} (bbls)= O\ BARREL
Notes: Volume estimation was done using an excel based tool.(see attached for details on the calculation) Reported spilled volume is an estimate Write other relevant notes taken into consideration for volume estimation or cause of spill:
Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on sit Conversion of m ² to barrels is Volume (m3) x 6.29: **Round up estimated volume to next whole number using the following rules: • Any spill volume in excess of 1 bbl — is rounded up to the next whole number.
 Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.
Examples: Calculated volume = 15.3 bbl Reported volume = 16 bbl Calculated volume = 0.35 bbl Reported volume = 0.4 bbl Calculated volume = 0.01 bbl Reported volume = 0.1 bbl.
Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for collectimation: record the calculation in a plain sheet of paper and attach to the JIV report
Version 2020/01 Distribution of copies: White (Asset Owner); Pink (DPR), Green (NOSDRA); Yellow (State Ministry of Environment);

Page 5 of 8

Blue (Host Community)

Scanned with CamScanner

INCIDENT NO: 3053329 JIV report S/N: 001019

d.	General	Status	of	the	site
----	---------	--------	----	-----	------

- i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out
- ii. Investigation of the incident site showed that there is residual impact on site requiring further works

e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:

- · Host Community: □
- Department of Petroleum Resources [DPR]: □
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:

 □
- The Shell Petroleum Development Company [SPDC]: ☐
- Separate DPR form has been filled out with same findings
- Separate NOSDRA form has been filled out with same findings
- Separate SME form has been filled out with same findings

Tick as applicable

Version 2020/01

Distribution of copies. White (Asset Owner), Pink (DPR), Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community). Page 6 of 8

INCIDENT NO: 3053329 JIV report S/N: 0001019

f. Appendix 1: Overview sketch of the site HOOK UP ARM OPUKUSH1 FLOW LINE NAT Location: AJATITOM WELL

Version 2020/01

Distribution of copies. White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community). Page 7 of 8