



Overview: Part of spill impact on 20" Kolocreek \_Rumuekpe Trunkline at Okoma. Picture was taken during Joint Investigation of 23<sup>rd</sup> September 2021.



Close-up: 8inch ball valve installed at 12 o'clock position on 20" Kolocreek \_Rumuekpe Trunkline at Okoma. Picture was taken during Joint Investigation of 23<sup>rd</sup> September 2021.