



Overview: Part of spill impact on 4" ImoRiver well 58T flowline at Odagwa.  
Picture was taken during Joint Investigation of 23<sup>rd</sup> September 2021.



Close-up: Missing Flowline on 4" ImoRiver well 58T flowline at Odagwa.  
Picture was taken during Joint Investigation of 23<sup>rd</sup> September 2021.