



Overview: Part of spill impact on 12" Oguta Egbema Pipeline at Umunkwu. Picture was taken during Joint Investigation of 10<sup>th</sup> September 2021.



Close-up: Crude oil theft point installed at 12 o'clock position on 12" Oguta Egbema Pipeline at Umunkwu. Picture was taken during Joint Investigation of 10<sup>th</sup> September 2021.