



Overview: Part of spill impact on Adibawa Well8S flowline right of way at Edagberi. Picture was taken during Joint Investigation of 10th April 2013.



Close up: Hacksaw cut on Adibawa Well8S flowline at Edagberi. Picture was taken during Joint Investigation of 10th April 2013.