



**Overview:** Part of spill impact on Imo River Well 31S 6" Flowline at Owaza. Picture was taken during Joint Investigation of 10<sup>th</sup> April 2018.



**Close-up:** Failed Half Inch Nipple on Imo River Well 31S 6" Flowline at Owaza. Picture was taken during Joint Investigation of 10<sup>th</sup> April 2018.