




**Overview:** Part of spill impact on on Bonny Well2L Flowline Right of Way at Erekeriri/Okolo Launch. Picture was taken during Joint Investigation of 18<sup>th</sup> January 2015.



**Close-up:** Spill due to corrosion on Bonny Well2L Flowline at Erekeriri/Okolo Launch. Picture was taken during Joint Investigation of 18<sup>th</sup> January 2015.