



Overview: Part of spill impact on Cawthorne Channel Well41S flowline right of way at Elemama. Picture was taken during Joint Investigation of 2nd January 2013.



Close up: Spill due to corrosion on Cawthorne Channel Well41S flowline at Elemama. Picture was taken during Joint Investigation of 2nd January 2013.