




Overview: Part of spill impact on 12" Imo River1 – Ogale Pipeline Right of Way at Uzuaku. Picture was taken during Joint Investigation of 20th February 2020.



Close-up: Leaking 2" Ball Valve Installed at 12 o'clock position on 12" Imo River1 – Ogale Pipeline at Uzuaku. Picture was taken during Joint Investigation of 20th February 2020.