



Overview: Part of spill impact on Opukushi Well24T flowline right of way at Agbidiamama. Picture was taken during Joint Investigation of 31st January 2013.



Close up: Bulge due to corrosion on Opukushi Well24T flowline at Agbidiamama. Picture was taken during Joint Investigation of 31st January 2013.