



Overview: Part of spill impact on Kanbo Well5L & S flowline right of way at Amabulu. Picture was taken during Joint Investigation of 19th January 2013.



Close up: Failed weld on Kanbo Well5L & S flowline at Amabulu. Picture was taken during Joint Investigation of 19th January 2013.



Close up: Failed weld on Kanbo Well5L & S flowline at Amabulu. Picture was taken during Joint Investigation of 19th January 2013.



Close up: Pinhole at 6 o'clock position on Kanbo Well5L & S flowline at Amabulu. Picture was taken during Joint Investigation of 19th January 2013.