




Overview: Part of spill impact on 4" Nkali Well10S Flowline Right of Way at Odagwa2. Picture was taken during Joint Investigation of 18<sup>th</sup> January 2016.



Close-up: Failed clamp on 4" Nkali Well10S Flowline at Odagwa2. Picture was taken during Joint Investigation of 18<sup>th</sup> January 2016.