



Overview: Part of spill impact on 20" Otumara-Escravos pipeline right of way at Ugboegungun. Picture was taken during Joint Investigation of 31st July 2013.



Overview: Part of spill impact on 20" Otumara-Escravos pipeline right of way at Ugboegungun. Picture was taken during Joint Investigation of 1st August 2013.



Close up: Illegal fitting on 20" Otumara-Escravos pipeline at Ugboegungun. Picture was taken during Joint Investigation of 29th August 2013.



Close up: Illegal fitting on 20" Otumara-Escravos pipeline at Ugboegungun. Picture was taken during Joint Investigation of 29th August 2013.



Close up: Illegal fitting on 20" Otumara-Escravos pipeline at Ugboegungun. Picture was taken during Joint Investigation of 31st July 2013.



Close up: Illegal fittings on 20" Otumara-Escravos pipeline at Ugboegungun. Picture was taken during Joint Investigation of 1st August 2013.



Close up: Illegal fitting on 20" Otumara-Escravos pipeline at Ugboegungun. Picture was taken during Joint Investigation of 1st August 2013.



Close up: Illegal fitting on 20" Otumara-Escravos pipeline at Ugboegungun. Picture was taken during Joint Investigation of 1st August 2013.